

These are pictures from the failure of an air compressor. The owner hadn't kept moisture from accumulating in the vessel, and ultimately it failed along one of the vessel's welded seams. Water will condense from the air and collect in the tank. If not drained periodically, this can happen. The tank also has a hydrotest interval, beyond which it shouldn't be used unless a hydrotest is performed by a competent person

Debris hit car in driveway



Debris hit car in driveway



Debris hit garage ceiling



Power cord whipped around and punctured bottle of antifreeze



Debris hit garage wall



Damage to wall beside where compressor



Cover guard off of compressor



