



All Foremen and leads;

Have your crews inspect all 4" grinding disks before use, the disk in question is the (Norton) Bluefire.4' grinding disk. During night shift, a pipe welder discovered this during operation. As the images show, the center ring (depressed) came apart while grinding. This had the potential of the abrasive portion breaking up and projecting fragments and injuring the worker and others in proximity. An immediate inspection and test (Mfg suggested) was conducted on all in stock disks and none were found to be defective. Your attention and vigilance is expected and most appreciated.

David "Tony Lewis, Wyatt Safety



GRINDING WHEEL
DISQUE DE MEULAGE
DISCO PARA DESBASTE

STEEL
ACIER
ACERO



STAINLESS/INOX

TYP
TYP
TIPO

27

4 1/2" x 1/4" x 5/8-11"

115 x 7mm x 5/8-11"