

Result of leaking **Acetylene** bottle stored in plumbers van 10-22-09. Accidentally ignited by activating a remote door lock device. Any friends in the industry or trades people please pass on.



