

A GE compressor package was under nitrogen pressure test. You can see the pipe had a brittle fracture failure. This is another illustration of the potential hazards of pneumatic testing.

This is for the expansion of the West-East Gas Pipeline project for PetroChina. It is China's longest natural gas pipeline at 2500 miles (4000 km).















